SDMS US EPA REGION V COLOR - RESOLUTION - 3 IMAGERY INSERT FORM

Multiple pages of this document include color or resolution variations and may be illegible in SDMS due to bad source documents. Unless otherwise noted, these pages are available in monochrome. (The source document page(s) are more legible than the images.) The original document is available for viewing at the Superfund Records Center.

SITE NAME	CHEMICAL RECOVERY
DOC ID#	147481
DOCUMENT VARIATION	_X_ COLOR OR RESOLUTION
PRP	RMD - CHEMICAL RECOVERY
PHASE	ENFORCEMENT
OPERABLE UNITS	
LOCATION	Box # Folder # Subsection
PHASE (AR DOCUMENTS ONLY)	Remedial Removal Deletion Docket Original Update # Volume of
	COMMENT(S)
	FOLDER M-57

Industrial Commission

147481





DIVISION OF SAFETY AND HYGIENE

2325 W. 5th AVE. P.O. BOX 1745 COLUMBUS, OHIO 43216 466-3385

Industrial Commission GREGORY J. STEBBINS Chairman MARGUERITE M. NEAL Vice Chairman JOHN E. SENN Member JOHN J. GILLIGAN Governor Division of Safety and Hygiene GARY B. BRYNER Superintendent

May 23, 1974

J. Freeman, General Manager Chitts Chemical Co. 142 Locust St. Elyria. Chio 44035

Dear Mr. Freeman:

A SAFETY SURVEY WAS MADE OF YOUR OPERATIONS, AT WHICH TIME CERTAIN CONDITIONS WERE OBSERVED THAT FAIL TO MEET OUR SAFETY STANDARD CODE REQUIREMENTS.

REFERENCE IS MADE TO IC-5, ''SPECIFY SAFETY REQUIREMENTS OF THE INDUSTRIAL COMMISSION OF OHIO RELATING TO ALL WORKSHOPS AND FACTORIES'', A COPY OF WHICH HAS BEEN PROVIDED.

CONDITIONS THAT FAIL TO MEET THE SAFETY STANDARD CODE REQUIRE- MENTS ARE LISTED ON THE REVERSE SIDE OF THIS LETTER.

Very truly yours.

John T. Danicki Safety Advisor

1-C

JTD: 16

110 S 347



FORM 706A - 5 1/74

THE INDUSTRIAL COMMISSION OF OHIO DIVISION OF SAFETY AND HYGIENE

		' IN						S, OHIO 43216 • 4				PAGE	_OF
1 = SU		ŀ	HOURS UNITS	SUG- DS GESTIONS		SAFETY ADVISOR NUMBER		RISK NUMBER IF SELF INSURED ADD S. I.	TOTAL* EMPLOYEES	DATE MO. DA. YR	2 = M 3 = N	(2) erit Roted W/Penolty erit Roted W/Oredit of Marit Roted	
	L	1	.₽ · t.		102	į (t	44	11.1573	के जा के जा	5 23 74			i.
	lii lera.	1		40 4				57	- 6		شفائه وخنعه أنبنب	90 	i i i i i i i i i i i i i i i i i i i
						EN ROLL	() () () () () () () () () () () () () (The spile of the first of the	A FRITTI DE			
. 66	DE.	- 11 11 1	ATIO		EG	UIPM	ENT (OR FACILI	ry Y	or handle being and the eld to	LOCA	TION OF	
I I. C. ER NUMBER	SECTIO	SECTIO	SUB-SU N SECTION			IN	VIOL	ATION				LATION	
. 2	2	+4	12	14	27	å						Jahr: III	
5	113	195			Tunt •	coun!	Lines			coller	Postu		
			. I'v A					a design of the second				t i de anna la color silver de la deca	Antonio de Maria de Caración de La Caración de Caració
		112		. And San	See			, and the second		1 1	11	in little of	ara o governo appeado
15		115	4.	65	iau -	aus rá	1 - 1	en la	*	**	51		
		1			en e			🕏 طورونية بهويونية بالمواقعة - دار - ي - از التواقعة				The state of the s	
2	23	03	in Ne	150	ing -	V be	i t	e de la companya de	- 1		C2-4	Control of the contro	photo and algorithms are shown in the second
4	m 175 2	13	1	30	Page -	count	Lina	:	- 18 K	Alcohol			
					and the second second		T. FL. BLOW		(er.)	. 01.13 5). 3	4	a to the second	
2	23	05	1	20	. 137 / * sue	count	Line	The second section of the sect		77			
				The state of the state of the same of the	e te destrutuique de la grand de la televisión de	1.49-1.11	The State of the S	The second secon		and the second second second		CONTRACTOR CONTRACTOR CONTRACTOR	
						nangan ang 10 mi		The state of the s					was to the same of the same
				And the state of t		AND CARLOS CARROLL CONTROLS C	mer mente tra	The state of the s	The second secon			The real of the second of	
										* - NO - N			
			42	- Justin	1.71							******	
		ļ											
				1000	40.35					4			
		775	100	NEED OF									
RST	7	• •	: ÷ 1	ndu, Ge Oranica	1	str e to:			list item no 's	from above acc	ordina to d	egree of compliance	
CHECK	(: ८					, (Compli	anco itam(c) no .		TIOM GEOVE GC	wanig io a	egree or compliance	z.
		MO.	DAY	YR. HOURS	SAFETY	2.	•	ance item(s) no.: compliance item(s)		De la Li		V-1, , , , , , , , , , , , , , , , , , ,	
	1		DATE 9 7	HUNDREI 1 72	DS ADVISOR	3.							
COND	-			<u> </u>			▼ Non-co	mpliance item(s) no		from above ass	ordina to d	egree of compliance	
COND CHECK	(; /					1.	■ Complic	ınce item(s) no.:				-p. vs. v. comprodice	-
		MO.		YR HOURS UNITS HUNDRE	INITALS SAFETY S ADVISOR	2.	3	compliance item(s)	no.:				
	1	7	DATE	7 78	40		. :	nplicinal item(s) no					
						J		مار (۱۱۸۵) معلق تحسب العام	·				



DIVISION OF SAFETY AND HYGIENE
2325 W. 5th AVE.
P.O. BOX 1745
COLUMBUS, OHIO 43216
466-3385

Industrial Commission GREGORY J. STEBBINS Chairman MARGUERITE M. NEAL Vice Chairman JOHN E. SENN Member JOHN J. GILLIGAN Governor

Division of Safety and Hygiene GARY B. BRYNER Superintendent

May 23, 1974

J. Freeman, General Manager Chitts Chemical Co. 142 Locust St. Elyria, Chio 44035

CODE VIOLATIONS

FIRST RECHECK SEE REVERSE SIDE BOTTOM

Dear Mr. Freeman:

A SAFETY SURVEY WAS MADE OF YOUR OPERATIONS, AT WHICH TIME CERTAIN CONDITIONS WERE OBSERVED THAT FAIL TO MEET OUR SAFETY STANDARD CODE REQUIREMENTS.

REFERENCE IS MADE TO IC-5, "SPECIFY SAFETY REQUIREMENTS OF THE INDUSTRIAL COMMISSION OF OHIO RELATING TO ALL WORKSHOPS AND FACTORIES", A COPY OF WHICH HAS BEEN PROVIDED.

CONDITIONS THAT FAIL TO MEET THE SAFETY STANDARD CODE REQUIRE-MENTS ARE LISTED ON THE REVERSE SIDE OF THIS LETTER.

Very truly yours,

John T. Deniek: Safety Advisor I_C

JTD:16



FORM 706A - 5

THE INDUSTRIAL COMMISSION OF OHIO DIVISION OF SAFETY AND HYGIENE

2325 W. 5th AVE. - P.O. BOX 1745 REPORT OF INDUSTRIAL SAFETY SURVEY COLUMBUS, OHIO 43216 • 466-3385 PAGE OF ① (6) 7 TOTAL DATE SOURCE SAFEZH ADVISOR NUMBER 1 = Merit Rosed W/Penalty HOURS TOTAL COUNTY RISK NÜMBER 1 = SURVEY F SELF INSURED 2 # Merit Rated W/Credit UNITS HUNDREDS SUG-DOCUMENT NUMBER EMPLOYEES GESTIONS NUMBER MO. DA. YR. ADD S. 1. 3 - Not Merit Rated 2500 40 LOCATION OF VIOLATION 105 20 Bottar Boom 20 IO5 M 65 James Trapped The Thirtie Pump -03 03 C 19 V belt Alcohol Process 5 03 05 A 20 Pump - coupling 03 05 20 coupling A. #igi 254 P. D4 B red fant. ork RECHECK: 2 List item no.'s from above according to degree of compliance. 6 JID 1. C Compliance item(s) no.: INITIALS SAFETY ADVISOR DAY Partial compliance item(s) no. DATE HUNDREDS 69 SECOND 7 List item no./s from above according to degree of compliance Compliance item(s) no.: INITALS SAFETY ADVISOR MO. DAY Partial ca DATE

Division of Safety and Hygiene 700 W. Third Avenue, Columbus, Ohio 43212

469-2870 🕾 469-3386



Industrial Commission M. HOLLAND KRISE Chairman

LLEWELLYN A. COLES Vice Chairman

JOHN P. SHEEHAN

JAMES A. RHODES Governor

Division of Safety and Hygiene

THOMAS W. GALLAGHER Superintendent

October 30, 1969

Mr. R. W. Obitts, President Chitta Chemical Co. 142 Locust St. Elyria, Chio 44035

CODE VIOLATIONS

FIRST RECHECK

SEE REVERSE SIDE BOTTOM

DEAR MR. Chitts:

A SAFETY SURVEY WAS MADE OF YOUR OPERATIONS, AT WHICH TIME CERTAIN CONDITIONS WERE OBSERVED THAT FAIL TO MEET OUR SAFETY STANDARD CODE REQUIREMENTS.

REFERENCE IS MADE TO IC-5, "SPECIFIC SAFETY REQUIREMENTS OF THE INDUSTRIAL COMMISSION OF OHIO RELATING TO ALL WORKSHOPS AND FACTORIES", A COPY OF WHICH HAS BEEN PROVIDED.

CONDITIONS THAT FAIL TO MEET THE SAFETY STANDARD CODE REQUIRE-MENTS ARE LISTED ON THE REVERSE SIDE OF THIS LETTER.

Safety Mivisor

AWLeib

"SAFETY DIRECTOR" to all Ohio industry

3. Non-compliance item(s) no.

Scusekeeping in Beiler Room needs immediate

Division of Safety and Hygiene
700 W. Third Avenue, Columbus, Ohio 43212
469-2870 469-3386



Industrial Commission
M. HOLLAND KRISE
Chairman
LLEWELLYN A. COLES
Vice Chairman

JAMES A. RHODES Governor Division of Safety and Hygiene

THOMAS W. GALLAGHER Superintendent

JOHN P. SHEEHAN Member October 30, 1969

Mr. R. W. Obitts, President Obitts Chemical Co. 142 Locust St. Elyria, Ohio 44035

DEAR MR. Obitts:

A SAFETY SURVEY WAS MADE OF YOUR OPERATIONS, AT WHICH TIME CERTAIN CONDITIONS WERE OBSERVED THAT FAIL TO MEET OUR SAFETY STANDARD CODE REQUIREMENTS.

REFERENCE IS MADE TO IC-5, "SPECIFIC SAFETY REQUIREMENTS OF THE INDUSTRIAL COMMISSION OF OHIO RELATING TO ALL WORKSHOPS AND FACTORIES", A COPY OF WHICH HAS BEEN PROVIDED.

CONDITIONS THAT FAIL TO MEET THE SAFETY STANDARD CODE REQUIRE-MENTS ARE LISTED ON THE REVERSE SIDE OF THIS LETTER.

Very truly yours.

A. W. Leach

1-E

Safety Advisor

AWL: ib

"SAFETY DIRECTOR" to all Ohio industry

THE INDUSTRIAL COMMISSION OF OHIO DIVISION OF SAFETY AND HYGIENE FORM 706A 5 REPORT OF INDUSTRIAL SAFETY SURVEY PAGE OF_ Columbus, Ohio 43212 Merit Rated W/Penalty 0. 0 $\overline{oldsymbol{\circ}}$ **①** 0 0 • ® TOTAL 1 RISK NUMBER HOURS TOTAL SOURCE SAFETY COUNTY DATE SURVEY **EMPLOYEES** 2 - Merit Ruted W/Credit UNITS SUG-DOCUMENT ADVISOR NUMBER IF SELF INSURED MO. DA. YR. 3 = Not Merit Rated HUNDREDS GESTIONS NUMBER NUMBER ADD S. I. 241 28ි 2:45 161673 10 30 ВО THE TROPIET LOCATION OF EQUIPMENT OR FACILITY IN VIOLATION VIOLATION ECTION SECTION NUMBER NUMBER 27 Water San Comment of the Comment 03 09 C 5 19 7 Chemical pumps - V belt Process Bldg. 11 05 5 65 A Pan - guard 02 03 Al 14 Cat walk - standard rail 04 03 24 Ala Ladder equatruction 02 06 17 AB Stairway - handrail ri e Ticd FIRST Loui gour List item no.'s from above according to degree of compliance. RECHECK: 1. C Compliance item(s) no.: _ DAY YR. SAFETY 2. Partial compliance item(s) no.: (CAPCECE 3) * TSO HUNDREDS 40 DATE 3. Non-compliance item(s) no.: SECOND List item no 's from above according to degree of compliance. RECHECK: 1. C Compliance item(s) no.: INITIALS SAFETY ADVISOR MO. DAY YR. HIMITS 2. Partial compliance item(s) no.: 3. Non-compliance item(s) no.:.___

Housekeeping in Boiler Room needs immediate ettestion.

TO	The Industria Div. of Safet 700 West Thir Columbus, Thi	d Svenue	FROM	OBITTS CHE 142 LOCUST S P. O. BOX S ELYRIA, OF FA 3-3278	TREET 375 IIO
SUBJECT	,			DATE:	11/11/69
FOLD A	<u>Gentlemen:</u> Would you	please provide to u	s, "Specia	tic Safety Regui	uements of the
		mmission of Ohio Rel			
	(9C-5).				
				Thank You,	
PLEASE	REPLY TO	SIGNED		Clara St. 8	af .
D. LONG		GIGNED			
DATE		SIGNED			

GRAYARC CO., BROOKLYN 32, N. Y.

DETACH THIS COPY - RETAIN FOR ANSWER. SEND WHITE AND PINK COPIES WITH CARBONS INTACT.

Division of Safety and Hygiene 700 W. Third Avenue, Columbus, Ohio 43212 469-3870 🕾 469-3386

October 30, 1969

Mr. R. W. Obitts, President Chemical Service Corp. 128 Locust St. Elyria, Ohio 44035

DEAR MR. Obitts:

A SAFETY SURVEY WAS MADE OF YOUR OPERATIONS, AT WHICH TIME CERTAIN CONDITIONS WERE OBSERVED THAT FAIL TO MEET OUR SAFETY STANDARD CODE REQUIREMENTS.

REFERENCE IS MADE TO IC-5, "SPECIFIC SAFETY REQUIREMENTS OF THE INDUSTRIAL COMMISSION OF OHIO RELATING TO ALL WORKSHOPS AND FACTORIES", A COPY OF WHICH HAS BEEN PROVIDED.

CONDITIONS THAT FAIL TO MEET THE SAFETY STANDARD CODE REQUIRE-MENTS ARE LISTED ON THE REVERSE SIDE OF THIS LETTER.

yours

A. W. Leach

1-**D**

Safety Advisor

awl:ib

"SAFETY DIRECTOR" to all Ohio industry

PORM 706A - 5

THE INDUSTRIAL COMMISSION OF OHIO PHOTON OF SAME Third Res

R	EPORT OF	IN	DUSTRIAL	SAFI	TY SURV	/EY		plumbus, Ohio			PAGEOF_
1	① 1 = SURVEY		UNITS HUNDREDS	TOTAL SUG- GESTIONS	SOURCE SOURCE DOCUMENT NUMBER	SAMPLY, ADVISOR NUMBER	COUNTY, NUMBER	THEK, NUMBER, IF SELF INSURED ADD S. I.	TOTAL EMPLOYEES	1 1	1. = Merit Rated W/Penalty 2 = Merit Rated W/Credit 3 = Not Merit Rated
		1	1:45	1	242	58	47	407747	4	10 30 9	3

•	ì. C.	SECTION	SUB		JB PAGE	EQU	IPMENT OR FACILITY IN VIOLATION	LOCATION OF VIOLATION
ER	1 1	2	SECTI- 2	ON SECTION	NUMBER	27		
-	5	03	03	c	19	Washer	- V belt	ME. Area -not in use
	5	03	05	. A	20	Washer .	- coupling	28 88
	5	03	03	С	19	Port, Po	um - V belt	
	5	03	05	À	20	Outside	mixer pump - coupling	
1	5	03			20		pumps - coupling	Tower Room
	5	02		1			y - handrail	Tower Room ordered
	5	08	03	Al	14	Catvelk	- standard rail	19 40
	5	03	09	1)		Port. h	and tools - ground	Boiler Room
	Ş.,	03	09	. ")	23	Pipe th	reader - ground	" " gone
				.				
1								
					r Regist			
T IE(CK:	2	21			ijae grad Jakan stro		s from above according to degree of compliance.
				DAY	YR. HOURS UNITS HUNDREDS	INITIALS SAFETY ADVISOR	2. P Partial compliance item(s) no.:	
		•	6	DATE 9 71	-	0	3. N Non-compliance item(s) no.:	
)Ni	D CK:	7	MO.	DAY	YR. HOURS	INITIALS SAFETY	List item no 1. C Compliance item(s) no.:	.'s from above according to degree of compliance.

Division of Safety and Hygiene 700 W. Third Avenue, Columbus, Ohio 43212

469-2870 🕾 469-3386

Industrial Commission M. HOLLAND KRISE Chairman

LLEWELLYN A. COLES Vice Chairman

JOHN P. SHEEHAN Member

JAMES A. RHODES Governor

Division of Safety and Hygiene

THOMAS W. GALLAGHER

October 30, 1969

Mr. R. W. Obitte, President Obitts Chemical Co. 142 Locust St. Elyria, Chio 44035

CODE VIOLATIONS

SECOND RECHECK

SEE REVERSE SIDE BOTTOM

DEAR MR. Obites:

A SAFETY SURVEY WAS MADE OF YOUR OPERATIONS, AT WHICH TIME CERTAIN CONDITIONS WERE OBSERVED THAT FAIL TO MEET OUR SAFETY STANDARD CODE REQUIREMENTS.

REFERENCE IS MADE TO IC-5. "SPECIFIC SAFETY REQUIREMENTS OF THE INDUSTRIAL COMMISSION OF OHIO RELATING TO ALL WORKSHOPS AND FACTORIES", A COPY OF WHICH HAS BEEN PROVIDED.

CONDITIONS THAT FAIL TO MEET THE SAFETY STANDARD CODE REQUIRE-MENTS ARE LISTED ON THE REVERSE SIDE OF THIS LETTER.

ery truly yours

Safety Mivisor

AVLaib

"SAFETY DIRECTO Ohio industry

COMMISSION OF OHIO THE INDUSTRIAL

700 West Third Ave. Columbus, Ohio 43212 REPORT OF INDUSTRIAL SAFETY SURVEY . ① MSK NUMBER 0 , ® SOURCE 1 = SURVEY IF MELF INSURED EMPLOYEES UNITS DOCUMENT ADVISOR NUMBER NUMBER 161673 FOLICIVING SAFETY IN VIOLATION 19 1 7 Chemical cumps - V belf Frocess Blag. 2 11 05 65 Fan - guard 3 14 Cat walk - standard rail da lob 04 OB Ale 24 Ladder construction 06 17 02 Stairway - handrail Office TELET? FIRST List item no.'s from above according to degree of compliance. RECHECK: AWI.
INITIALS
SAFETY
ADVISOR 1. C Compliance item(s) no.: 2,3,4 and suggestion. 2. P Partial compliance item(s) no. 3. Non-compliance item(s) no.: 1 and 5. SECOND List item no.'s from above according to degree of compliance. 1. C Compliance item(s) no.: 1 and 5. Partial cappliance item(s) no.: Housekeeping in Boiler Room

Industrial Commission
M. HOLLAND KRISE
Chairman

Division of Safety and Hygiene
700 W. Third Avenue, Columbus, Ohio 43212
469-2870 🕾 469-3886

Division of Safety and Hygiene

THOMAS W. GALLAGHER Superintendent

Vice Chairman JOHN P. SHEEHAN Member

LLEWELLYN A. COLES

June 6, 1973

R. W. Chitte, President Chitts Chemical Co. 142 Locust St. Elyria, Chio 44035

CODE VIOLATIONS

FIRST RECHECK

SEE REVERSE SIDE BOTTOM

DEAR MR. Obitts:

A SAFETY SURVEY WAS MADE OF YOUR OPERATIONS, AT WHICH TIME CERTAIN CONDITIONS WERE OBSERVED THAT FAIL TO MEET OUR SAFETY STANDARD CODE REQUIREMENTS.

REFERENCE IS MADE TO IC-5, "SPECIFIC SAFETY REQUIREMENTS OF THE INDUSTRIAL COMMISSION OF OHIO RELATING TO ALL WORKSHOPS AND FACTORIES", A COPY OF WHICH HAS BEEN PROVIDED.

CONDITIONS THAT FAIL TO MEET THE SAFETY STANDARD CODE REQUIRE-MENTS ARE LISTED ON THE REVERSE SIDE OF THIS LETTER.

very truly yours,

John T. Danieki 1-C Safety Advisor

JTD:1b

"SAFETY DIRECTOR" to all Ohio industry

Comments:

THE INDUSTRIAL COMMISSION OF OHIO DIVISION OF SAFETY AND HYGIENE 700 West Third Ave. Columbus, Ohio 43212

PAGE 1 OF1 REPORT OF INDUSTRIAL SAFETY SURVEY 1 = Merit Rated W/Penalty • • n • 10 TOTAL EMPLOYEES • \odot HOURS TOTAL SOURCE SAFETY COUNTY RISK NUMBER DATE 1 = SURVEY 2 = Merit Rated W/Credit UNITS SUG-DOCUMENT ADVISOR NUMBER IF SELF INSURED MO. DA. YR. GESTIONS HUNDREDS NUMBER NUMBER ADD 5.1. 3 = Not Merit Rated 407747 2:00 149 16 47 13 6 6 73

		!	<u> </u>	****	40	12 47	49 51	57	62	67	80			
	tii kt. S						NS OBSERV	A SALES						.
	C	ODE	VIOL	ATION										r Y
ITEM	1. C.	1	SUB-	SUB-SUB	PAGE	EQUI	IPMENT OR I		Ī	LO	CATION	OF		
NUMBER	NUMBER	60 4 1	SECTIO	N SECTION	NUMBER	- 11k - 4	IN VIOLATIO	ON		V	OLATION	V		
>2_	2	2	2	2	4	27								ر
1.	5	02	04	1	16	Platform	a (Intermedi	ate rail a	ton bot	ard)	Plant			
2	5	03	06	В	53	Shop pun	o - man				· · · · · · · · · · · · · · · · · · ·			
3	5	03	03	С	19	Pump Ho.	1 - V belt	energia de la Companya de la Company	81	TOPA YOU	Teor •			ECK
4	5	03	03	c	19	Pump No.	, 2 - * *	 	20	A		3-C		HECHECK
5	5	03	05		20	Receivin	ig tenk No.	1 - coupli	No. of				P.S.	FIRST
6	5	03	05		80		No.	5 - 4		er erely				F4-4
7	5	63	05	A	20	Croulat	ing tenk		-				5	
b	5	09	05	1	57	Grinder	- teol rest	•			Boiler	Room		and the second of the second of
9	5	10	04	8	58		safety 63				. *			
λÜ	5	03	05	A	20	Water pu	amp – compli	ne			*	**		
					***** Q					and the second s		e de la companya de l		
•			₫ £ 	:					Sunda Ingaria anak			Plat in		
				-	t.s.									
			e pa Tass	12.0	ent St. Onito	1035								
FIRST		7	27			GO.		List iter	m no.'s from ab	oove according	to dearge of co	ompliance.		1
RECH	tun:	<i>-</i>	MO.	DAY Y		SAFETY	1. C Compliance its	em(s) no.:		. market and market for		*		
		,	69	ATE 71	HUNDRED:	· '		ance item(s) no.:	•		73	***		-
					1	- 3	3. Non-complian			2,3,4,3,				=
SECO RECH	ND ECK:	7	MO.	DAY Y	Heurs	INTRALS	1-C Compliance in	em(s) no.:	m no.'s from ab	ove according t	to degree of co	mpliance.	He Mills	-
	145 145	1	- 1	ATE	HUMBRED	1		ance item(s) no.:	partiti Maray	· · · · · · · · · · · · · · · · · · ·		,;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;	41 P-21 13 - 73 -	-
							3. N Non-complan		The second secon					
						5 te - 1 to	ara a the March	112944	and the second	1 . A		Califor Ma	11.0	10.5

The second section of

Division of Safety and Hygiene
700 W. Third Avenue, Columbus, Ohio 43212
469-2870 & 469-3386



Industrial Commission
M. HOLLAND KRISE
Chairman
ILEWELLYN A. COLES
Vice Chairman

JOHN P. SHEEHAN Member Division of Safety and Hygiene

THOMAS W. GALLAGHER
Superintendent

June 6, 1973

R. W. Obitta, President Obitts Chemical Co. 142 Locust St. Elyria, Ohio 44035

CODE VIOLATIONS

SECOND RECHECK

SEE REVERSE SIDE BOTTOM

DEAR MR. Obitts:

A SAFETY SURVEY WAS MADE OF YOUR OPERATIONS, AT WHICH TIME CERTAIN CONDITIONS WERE OBSERVED THAT FAIL TO MEET OUR SAFETY STANDARD CODE REQUIREMENTS.

REFERENCE IS MADE TO IC-5, "SPECIFIC SAFETY REQUIREMENTS OF THE INDUSTRIAL COMMISSION OF OHIO RELATING TO ALL WORKSHOPS AND FACTORIES", A COPY OF WHICH HAS BEEN PROVIDED.

CONDITIONS THAT FAIL TO MEET THE SAFETY STANDARD CODE REQUIRE-MENTS ARE LISTED ON THE REVERSE SIDE OF THIS LETTER.

Very truly yours,

John T. Danicki

Safety Advisor

1-

JTD:ib

"SAFETY DIRECTOR" to all Ohio industry

THE INDUSTRIAL COMMISSION DIVISION OF SAFETY AND THE TOTAL TO West Third Ave. ETY SURVEY Columbus, Ohio 43212

DEDODE	OF	INDUCTORAL	C & Tritring	CITOTIES	~*
REPORT	Or	INDUSTRIAL	DATELL	DOMAGI	Co

 				· · · · · · · · · · · · · · · · · · ·		010112000, 01110		300			AND DESCRIPTION OF THE PARTY OF	the explanation	42
① 1 = SURVEY	HOURS UNITS HUNDREDS	TOTAL SUG- GESTIONS	(I) SOURCE DOCUMENT NUMBER	SAFETY ADVISOR NUMBER	① COUNTY NUMBER	RISK NUMBER A IF SELF INSURED ADD S. 1.	TOTAL EMPLOYEES	TAD NO DM	ne ili	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	D Test W/C Test Rotec		
1	2:00		149	16	47	AOTTA7	13	66	m L		Wird J		1
1	40	42	47	49	51	57	62	la de	1 67	- 40	San San		

	CODE VIOLATIONS OBSERVED FOLLOWING SAFETY STANDARD													
ITEM NUMBER), C.	SECTION	SUB SECTION	SUB-SUB SECTION 2	S PAGE NUMBER 4		PMENT OR FACILITY IN VIOLATION			CATION VIOLATI	SN .			
؞ؙ؞	5	02	O4	in .	1 6	Flatform	(Intermediate rail	8 too box	era)	Plant				
ii:	5	03	06	Š	a :	Shop pus	p - grans							
3	5	03	93	C	19	Pump No.	1 - V belt		renda M					
i c	5	03	03	C	1 0	Pump No.	2 m ³⁴ H							
	5	03	05	A	S C:	Receiving	g tank No. 1 - coup	ling						
į.	5	03	05	A	20	36	* No. 2 - *							
e e	5	03	05	A	50	Circulati	ing tank "		u na Linguis					
1.	5	09	05		57	Gränder -	- tool rest	::g'''		Red ler	No one			
đ.	5	10	9 4	A	- 58	. 9∌	safety glasses							
14	5	03	05	A	20	Water pu	mp - coupling			, **				
									F					
					(P)	ata :			£ . •			2-x 384		
	and the same		:		· · · · · · · · · · · · · · · · · · ·		Andrew Color State of State Comment of the State of State	The second secon						
							Tig et a		i de la compania del compania del compania de la compania del la compania de la compania del la compania del la compania de la compania del la compania d			16		
				Lates East	A P S A.	1033				. The American				
FIRST RECH	ECK:	2	ા^7 ફ કુ ? ફ	11,3	1,260	Treatment 1		item no.'s from al	bove accordin	g to degree o	f compliance.			
				DAY YI	HOURS UNITS HUNDRED	CAFETY	Compliance item(s) no.: P Partial compliance item(s) no.:		### (* 1	973				
		1	69	, 7 1	72	[,	3. Non-complidance item(s) no.:	1,	,2,3 ₄ 4,5	6.7.8	7,19,			
SECO RECH	ND ECK:	7		4 73	1:30 Hours	JPD	List Compliance item(s) no.:	item no.'s from al			Compilipines.			
	- 1	,	MO. L	ATE	HUNDRED 4	S ADVISOR 2	Partial compliance item(s) no.	:	#1 A1	*	44.44			
			وم	77	78	3	8. Non-compliance item(s) no.:	3,4,10.	<u> </u>	1 1				
Con	ments:											ÆĽ.		

Division of Safety and Hygiene
700 W. Third Avenue, Columbus, Ohio 43212
469-2870 🕾 469-3886



Industrial Commission
M. HOLLAND KRISE
Chairman
LLEWELLYN A. COLES
Vice Chairman

Division of Safety and Hygiene

THOMAS W. GALLAGHER Superintendent

JOHN P. SHEEKAN Member

June 6, 1973

R. W. Coitts, President Coitts Chemical Co. 142 Locust St. Elyria, Chio 44035

DEAR MR. Obitts:

A SAFETY SURVEY WAS MADE OF YOUR OPERATIONS, AT WHICH TIME CERTAIN CONDITIONS WERE OBSERVED THAT FAIL TO MEET OUR SAFETY STANDARD CODE REQUIREMENTS.

REFERENCE IS MADE TO IC-5, "SPECIFIC SAFETY REQUIREMENTS OF THE INDUSTRIAL COMMISSION OF OHIO RELATING TO ALL WORKSHOPS AND FACTORIES", A COPY OF WHICH HAS BEEN PROVIDED.

CONDITIONS THAT FAIL TO MEET THE SAFETY STANDARD CODE REQUIRE-MENTS ARE LISTED ON THE REVERSE SIDE OF THIS LETTER.

Very truly yours,

John T. Danicki

Safety Advisor

JTD:ib

"SAFETY DIRECTOR" to all Ohio industry

FORM 706A - 5 1/1/70

THE INDUSTRIAL COMMISSION OF OHIO DIVISION OF SAFETY AND HYGIENE 700 West Third Ave. Columbus Ohio 43212

REPORT OF II	NDUSTRIA	SAF	ETY SURV	/EY		olumbus, Ohi			P	AGE 1	OF ¹
① 1 = SURVEY	HOURS UNITS HUNDREDS	TOTAL SUG- GESTIONS	SOURCE DOCUMENT NUMBER	SAFETY ADVISOR NUMBER	② COUNTY NUMBER	RISK NUMBER IF SELF INSURED ADD S. I.	TOTAL EMPLOYEES	11) DATE MO. DA. YR.		® ted W/Penalty ted W/Credit it Rated	
/ Le 1	2:00		149		47	407717	1	6 6 73	3		
1	. 40	42	47	49	51	57	62	67	80		

			1	\$# 1; \$ <u>;</u> 3	40	12 47	49 51	57	62	67 80	
					ac n	VIOLITH	ONS PREEFVER	FOLLOWIN	G SAFETY	SURVEY	
ITEM NUMBER	I. C.	SECTIO	SUB-	SUB-SUB	·	EQU	JIPMENT OR FA		Mark Admin Mark on Theory	LOCATIO VIOLA	
_1 _	2	2	2	2	4 .	27		e e e e e e e e e e e e e e e e e e e			
		02	04	a.	16	Flatfor	m (Intermediat	e redi & to	e board)	Dian	
<u>.</u>		03.	06		23	Shop pu	Dy - gears			25	
4		3.	03	C	19	Flam No	. 1 - V belt		1 0 m a c c	Nijakjacz	
4	5	03	03	C	19	Purp No	. 2 "			S. Saud a tt	T. 49
E	it." Jahr	03	05	A.	20	Receivi	ng tank No. 1	- coupling			
ŧ,		03	35	Å	20	**	" No. 2		, Aerik	prieje 1. S s	
ř	\$	03	U5	A	20	Circula	ting tank			97	
ъ	2	99	05		57	Grinder	- tool rest			Boi 1	er Room
J	5	3.0	04	3	58	**	safety glas	S(†8			10 V
	5	úЗ	05	1	50	Water p	ump - coupling			57	₹# :.
*					: . : .					e eg∰g († 1747) Pergyali	e de la companya de
					Min	p#0:	V				
. 42							e emparation of				
			3.3	∵ 20 3 ∵ - C G1		#035					
FIRST RECH		2	. O	្នាយ់ (• ម	HOURS	initials Testicent	1. C Compliance item(s			cording to degre	e of compliance.
		. 1	D	DAY YE ATE	HUNDRED:	SAFETY	2. P Partial compliance	e item(s) no.:	្សាធាទ	(, 1973 _,	
		1	69	71	72		3. Non-campliance is	tem(s) no.:			
SECO RECH	ND ECK:	7					1. C Compliance item(s			cording to degre	e of compliance.
:	ing Nation	1	1	AY YE	HOURS UNITS HUNDRED	INITIALS SAFETY ADVISOR	2. P Partial compliance	e item(s) no.:		•	
p. (8)	. 18	•	75	77	78	,	3. Non-compliance it				
	-						L		H ON A		
Com	ıments:								Light of		